



Machine Specifications

Machine Voltage

220V
Single Phase
3 wire
60HZ 50Amp

Working Area

X Y Axis: 4' x 4'

Nominal: 51" x 51"

Z Axis: 9in travel

Vacuum Table

Bakelite Vacuum Table Surface

Multi-Zone Vacuum Table

T-Slot Clamping Table

Machine Structure

Welded Frame (same as larger machines) Detachable Legs

Spindle

Air Cooled Spindle 12 hp

24,000 RPM

Tool Cooling

Oil Mist & Air Cooling System

Motor & Drive

750 Watt Delta
Drives with 10 to 1
Reduction Box

Control System

HC-203C Handheld Pendant

Auto Tool Changer

Pneumatic 8 Tool
Changer with
ISO130

Pneumatic Rollers

Automatic Roller with 600lbs of adjustable pressure at each roller

Tool Sensor

Touch probe for Z axis zero of current tool and G54 Setting

Lubrication System

Oil lubrication system with manual pump

Machine Weight

1850lbs

Motion Supports

Linear Guide: XY with rack & pinon drive.

Linear Guide: Z with rack & pinon supports.

Ball Screw: on Z axis with hardened ball screw.

Rack 1.25M Taiwan J&T / Rack has dust cover.




GET IN TOUCH

(252) 229-3896

info@phantomcncsystems.com www.phantomcncsystems.com

276 Bailey Lane Vanceboro, NC 28586

Machine Dimensions



Shipping Dimensions

These dimensions are the overall dimensions of the equipment wrapped on a pallet.

82"(L) x 87"(W) x 85"(H)

Shipping cost vary on address and current carrier rates. Please contact for shipping quotes. Forklifts with 4ft forks are required.

Vacuum Pumps


The 2.2KW rotary vane pumps are big power in a small package. One pump is more than enough to handle most situations. Powered on a 30 amp 220v single phase line, no VFD needed. Sold separately.

Dust Collection

Phantom CNC Systems offers several levels of dust collection to meet your needs. Our line-up of dust collectors include pleated filters. Sold separately.

- Bakelite Vacuum Table Surface
- 2 Pneumatic Rollers
- 3 Vacuum Multi-Zone Controls
- 4 Emergency Stop Button
- **5** Air Pressure Gauge
- **6** T-Track Clamping System
- Air-cooled 12 HP 9KW Spindle
- 8 Rigid Tube Steel Gantry
- 9 Dust Boot
- Fully Welded Steel Frame with Removable Legs





- Mist Cooling Lubrication Tank 11
 - **Emergency Stop Button 12**
 - 8 Position Tool Rack 13
 - Oil-Mist Cooling System 14
 - Z Axis Lubrication Tank (5)
 - XY Lubrication Tank 16
 - Air Pressure Gauges 17
 - Heavy Duty Leveling Casters (18)
 - Gantry Wiring Access Point 19
 - Data Tag 20

Welcome Package

- Swag Bag
- 1/4" Collet
- 1/2" Collet
- Collet Nut
 - 1 Dust Hose

- Dust Boot
- Spanner Wrench
- 1 Tool Calibration Probe
- 1 Dust Rack (N/A on SCA machines)
- 1 Vacuum Hose (N/A on SCA machines)
- 4 Tool Holders (ATC machines only)



FINANCING AVAILABLE